【Control Software Installation Procedure】 for Windows10

1 Double click"LumitesterPD-30_Setup.exe" and start.
Please wait till all the files for Installation is completed.

30% Extracting	×

Cancel

2 Click "Lumitester Control Software"

Lumitester Control Software   ×

Manual

Lumitester Control Software

CANCEL

3 Click "Yes" when setup is started.

Lumitester Control Softwar   ×

?   Do you want to install Lumitester PD-30?

Yes   No

4 Installation is now ready, Click "Next"

5 Confirm the contents of License.
Select "Agree" to agree and then click "Next"
If you do not agree, click "Cancel"

6 Click "Yes" if you prefer to have shortcut on the desktop,
  If not, select "No" then click "Next".

Lumitester PD-30 Control Software   —   □   ✕

Shortcut

Do you want to place a shortcut on the desktop?

◉ Yes
○ No

[Cancel]   [< Back]   [Next >]

7 Enter the name of folder to Install.
  Click "Next" if there are no changes.

Lumitester PD-30 Control Software   —   □   ✕

Select Installation Folder

The installer will install Lumitester PD-30 Control Software to the following folder.

To install in this folder, click "Next". To install to a different folder, enter it below or click "Browse".

Folder:

C:\Program Files (x86)\Lumitester PD-30\   [Browse...]

[Disk Cost...]

Install Lumitester PD-30 Control Software for yourself, or for anyone who uses this computer:

◉ Everyone
○ Just me

[Cancel]   [< Back]   [Next >]

8 Click "Next"

9 Installation is now in progress.

10 Installation is complete
   Click "Close" to close the window.

Lumitester PD-30 Control Software

Installation Complete

Lumitester PD-30 Control Software has been successfully installed.

Click "Close" to exit.

Please use Windows Update to check for any critical updates to the .NET Framework.

Cancel   < Back   Close